


The Recovery Mode is only working with the Colibri T20 module




















X1P




1473005-1

PIN\_45  
PIN\_55  
PIN\_63  
PIN\_100  
PIN\_102  
PIN\_104




GPIOs\_SODIMM0\_51







Title <i><b>Evaluation Board 3.1</b></i>			Toradex AG Altsagenstrasse 5 Horw 6048 Switzerland
Size: <b>A3</b>	Number:	Revision:	
Date: <b>23/08/2013</b>	Time: <b>16:36:14</b>	Sheet <b>8</b> of <b>22</b>	
File: <b>GPIOs.SchDoc</b>			










X1L


















Unified Interface Display Connector














Title <i><b>Evaluation Board 3.1</b></i>			Toradex AG Altsagenstrasse 5 Horw 6048 Switzerland
Size: <b>A3</b>	Number:	Revision:	
Date: 23/08/2013	Time: 16:36:15	Sheet 20 of 22	
File: LEDs_Switches.SchDoc			



